




1430277
V1000 Casing - Battery Cover



1430277
V1000 Casing - Battery Cover



1430320
V1000 Transducer



1430288
V1000 Battery Clip 4 x AA



Service Repair Sheet SRS69404

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Mr Mahesh Shetty

BDI India Private Limited

Customer Support

Sr. Professional Customer Support

918022560418

918022560418

00006454

mahesha@bdi-india.com

20/Apr/2026

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes Customer would like to send in 10 x V1000 for calibration as usual. Some devices have missing parts, see their list in attached email please. The s/n are as follows: PR02540A13, PR02540A14, PR02529A20, PR02529A17, PR02529A22, PR02529A14, PR02380A12, PR02529A15, PR02529A18 and PR02529A11. I will mention that we need the devices to be cleaned or they will be charged a fee. They have not taken any notice of this in the past and always pay that fee. Will ask for cert of decontamination and no batteries and SRS number on all paperwork

10/Apr/2026 Kate Griffiths

Customer would like to send in 10 x V1000 for calibration as usual. Some devices have missing parts, see their list in attached email please. The s/n are as follows: PR02540A13, PR02540A14, PR02529A20, PR02529A17, PR02529A22, PR02529A14, PR02380A12, PR02529A15, PR02529A18 and PR02529A11. I will mention that we need the devices to be cleaned or they will be charged a fee. They have not taken any notice of this in the past and always pay that fee. Will ask for cert of decontamination and no batteries and SRS number on all paperwork

15/Apr/2026 Kate Griffiths

update: ps sorry the above is on 2x it was not done intentionally and I have no idea why it happened... they require CALIBRATION ONLY and agree to pay cleaning fee if needed. Email attached. Items on their way...

20/Apr/2026 Robert Connor

Received 10 x V1000 s/n PR02380A12, PR02529A11, PR02529A14, PR02529A15, PR02529A17, PR02529A18, PR02529A20, PR02529A22, PR02540A13, PR02540A14, with 6 x grey cover, missing 2 battery doors.

Units have obviously not been cleaned since they were last serviced and need deep clean before testing.

Ready For quote

Repair Complete Signed

CONTACTS 1430288
BATT DOOR 1430277
SPEAKER 1430320

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38725	Foetal Simulator	1410000	PR02380A12	✓
SRN38726	Foetal Simulator	1410000	PR02529A11	✓
SRN38727	Foetal Simulator	1410000	PR02529A14	✓
SRN38728	Foetal Simulator	1410000	PR02529A15	✓
SRN38729	Foetal Simulator	1410000	PR02529A17	✓
SRN38730	Foetal Simulator	1410000	PR02529A18	✓
SRN38731	Foetal Simulator	1410000	PR02529A20	✓
SRN38732	Foetal Simulator	1410000	PR02529A22	✓
SRN38733	Foetal Simulator	1410000	PR02540A13	✓
SRN38734	Foetal Simulator	1410000	PR02540A14	✓

Reverted back.

TIC DONE
TD
TD
TD
TD
TD
TD
TD
TD
TD
TD

TRANSDUCER
BATT DOOR

CONTACTS
BATT DOOR

changed
SIN CY

20-7-27