

Service Repair Sheet 69367

Contact Name	Christian Rose
Company/ Hospital Name	Sauerstoff Sensoren
Direct Phone	00492017587731
General Phone	492017587731
Opera Account	00006063
Email	info@sauerstoffsensoren.de
Date Received	10/Mar/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38572	0110117	220780	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376866.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38573	0110117	220781	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376867.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38574	0110117	220782	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376868.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38575	0110117	220783	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376869.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38576	0110117	220784	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376870.

Service Repair Sheet 69367

Contact Name	Christian Rose
Company/ Hospital Name	Sauerstoff Sensoren
Direct Phone	00492017587731
General Phone	492017587731
Opera Account	00006063
Email	info@sauerstoffsensoren.de
Date Received	10/Mar/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38577	0110117	220785	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376871.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38578	0110117	220786	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376872.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38579	0110117	220787	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376873.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38580	0110117	220788	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376874.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38581	0110117	220789	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376875.

Service Repair Sheet 69367

Contact Name	Christian Rose
Company/ Hospital Name	Sauerstoff Sensoren
Direct Phone	00492017587731
General Phone	492017587731
Opera Account	00006063
Email	info@sauerstoffsensoren.de
Date Received	10/Mar/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38582	0110117	220790	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376876.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38583	0110117	220791	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376877.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38584	0110117	220792	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376878.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38585	0110117	220793	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376879.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38586	0110117	220794	Oxygen Sensor	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced F.O.C. with S/N 376880.

