

Service Repair Sheet 69463

Contact Name	Stephen Machin
Company/ Hospital Name	Prosol UK Sales & Distribution Ltd
Department	Purchasing/Sales
Position	Operations Manager
Direct Phone	01142557700
General Phone	01142557700
Opera Account	00020046
Email	stephen@prosol.co.uk
Date Received	01/Jul/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38894	0110365	P107598	Oxygen Sensor	No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38895	0110365	P107729	Oxygen Sensor	No Fault Found
				Time :0 Hour(s)

To be credited.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38896	0110365	P107848	Oxygen Sensor	No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38897	0110365	P107864	Oxygen Sensor	No Fault Found
				Time :0 Hour(s)

To be credited.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38898	0110365	P107871	Oxygen Sensor	No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38899	0110365	P107873	Oxygen Sensor	No Fault Found
				Time :0 Hour(s)

To be credited.

Service Repair Sheet 69463

Contact Name	Stephen Machin
Company/ Hospital Name	Prosol UK Sales & Distribution Ltd
Department	Purchasing/Sales
Position	Operations Manager
Direct Phone	01142557700
General Phone	01142557700
Opera Account	00020046
Email	stephen@prosol.co.uk
Date Received	01/Jul/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38900	0110365	P108006	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38901	0110365	P108085	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38902	0110365	P108278	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	
SRN38903	0110364	P100613	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.