

Visit Report

System Ref: 33
Arrival Time: 12-08-2026 15:17:23
Departure Time: 12-08-2026 15:17:00
Call Type: Additions/Alterations



Unit 4 & 5 Enterprise Park
Keighley
West Yorkshire
BD21 4LN
TEL: 01535 661197

Client Name: Viamed Ltd
Client ID: 1819
Visit ID: 62522

Accounting No.: F6179
Work Order ID: 846962

Address: 15 STATION ROAD, CROSSHILLS, KEIGHLEY, BD20 7DT

Reason for call: ss Labour:1m1day take smoke pole and head remover for good out detectors (F6179)
Q54838

Engineer Notes: Please put photos / videos of installation work in the Installation Gallery on teams.
Replace the existing smoke/heat heads for new , there is a diagram below the fire alarm panel which shows the location of each head that you can work off as is a bit of a maze
Mick quoted:£1100.00+vat INVOICE 250367 -PAID

System Details

System Type	Fire Alarm	Category	L4
System Name	Viamed Ltd 15 Station Road	Signal Type	Audible Only Fire Alarm
Build Standard	Fire Detection and Alarm System BS5839 Pt 1		
Installation	10-04-2013		

CHECKLIST

Historical log up to date:	✓	Verification Acceptable:	0
Number of zones left on test:	0	Addressable Loop Resistance Reading L-L Ω:	0
Causes of false alarms eliminated:	✓	Addressable Loop Resistance Reading N-N Ω:	0
Reset the system:	✓	Addressable Loop Resistance Readings E-E Ω:	0
System free from false alarms:	✓	Loop/Zone Insulation Resistance L-E (MΩ):	0
System date/time correct:	✓	Loop/Zone Insulation Resistance L-N (MΩ):	0
Removed all tamper/remote links:	✓	Loop/Zone Insulation Resistance N-E (MΩ):	0
Power Supplies:	Main CIE	Conventional Circuit/Sounder Loop Resistance L-E (Ω):	0
Location:		Conventional Circuit/Sounder Loop Resistance N-E (Ω):	0
under panel		System off test with ARC:	N/A
I1 - Quiescent Current (A):	0	Line isolators Tested Open/Close circuit:	N/A
I2 - Alarm Current (A):	0	Any failures listed below:	0
T1 - Required Standby (Hours):	0	Sounder Circuits Tested Open/Close Circuit:	✗
Battery size fitted (Ah):	0	Any failures listed below:	0
Cmin - Minimum Battery Required (Ah):	0.0	Metre Used:	0
Battery Charge (V):	0	Calibration Date:	0
Battery Fault Tested:	✗	Next Date Calibratin Due:	0
Mains Fault Tested:	✗		

SUMMARY

Further visit required?:	✗	Further action required by customer:	✗
--------------------------	---	--------------------------------------	---

Visit Report

System Ref: 33
Arrival Time: 12-08-2026 15:17:23
Departure Time: 12-08-2026 15:17:00
Call Type: Additions/Alterations



Unit 4 & 5 Enterprise Park
Keighley
West Yorkshire
BD21 4LN
TEL: 01535 661197

Client Name: Viamed Ltd
Client ID: 1819
Visit ID: 62522
Accounting No.: F6179
Work Order ID: 846962

Address: 15 STATION ROAD, CROSSHILLS, KEIGHLEY, BD20 7DT
Reason for call: ss Labour:1m1day take smoke pole and head remover for good out detectors (F6179)
Q54838
Engineer Notes: Please put photos / videos of installation work in the Installation Gallery on teams.
Replace the existing smoke/heat heads for new , there is a diagram below the fire alarm panel which shows the location of each head that you can work off as is a bit of a maze
Mick quoted:£1100.00+vat INVOICE 250367 -PAID

System Details			
System Type	Fire Alarm	Category	L4
System Name	Viamed Ltd 15 Station Road	Signal Type	Audible Only Fire Alarm
Build Standard	Fire Detection and Alarm System BS5839 Pt 1		
Installation	10-04-2013		

Notes & Signatures	
Engineer Notes: swap all smoke and heat heads for new all tested and working	
Engineer Signature - Gina Phillips: 	Client Signature - Lamb 



System Ref: 33
Arrival Time: 12-08-2026 15:17:23
Departure Time: 12-08-2026 15:17:00
Call Type: Additions/Alterations

Unit 4 & 5 Enterprise Park
Keighley
West Yorkshire
BD21 4LN
TEL: 01535 661197

Client Name: Viamed Ltd
Client ID: 1819
Visit ID: 62522

Accounting No.: F6179
Work Order ID: 846962

Address: 15 STATION ROAD, CROSSHILLS, KEIGHLEY, BD20 7DT

System Details

System Type	Fire Alarm	Category	L4
System Name	Viamed Ltd 15 Station Road	Signal Type	Audible Only Fire Alarm
Build Standard	Fire Detection and Alarm System BS5839 Pt 1		
Installation	10-04-2013		

MODIFICATION OR EXTENSION CERTIFICATE

A subsequent visit is required to complete the works:

Extent of system covered by this certificate:
upgrade of all smoke and heat heads

The extent of liability of the signatory is limited to the system described below:
Q54838

Variations from the recommendations of BS5839-1:2025 Clause 4.5 or 4.6:

Following the extensions or modifications, the system has been either recommissioned in accordance with the recommendations of BS5829-1:2025, 4.5.3, or tested in accordance with the recommendations of BS 5839-1:2025, 46.1.5 and 46.1.6:

Following the extensions or modifications, as-fitted drawings and other system records have been updated as appropriate:

Subsequent visit details (if required):

Engineer & Client Signatures

I/we being the competent person(s) responsible (as indicated by my/our signatures below) for the extension or modification of the fire detection and fire alarm system, particulars of which are set out below, CERTIFY that the said extension or modification work for which I/we have been responsible has to the best of my/our knowledge and belief been carried out in accordance with the recommendations of BS 5839-1:2025, Clause 45 or Clause 46 respectively, except for the variations, if any, stated in this certificate.

Date: 12-08-2026

Engineer Signature - Gina Phillips:



Client Signature - Lamb:

