

Service Repair Sheet SRS69435

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Lars Erik Stensvehagen
Modul Nordic AS

Sales and Product Manager
4762547110
62547110
00007592
lars.erik@modulnordic.no

03/Aug/2026
Robert Connor
Viamed
Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 19/May/2026 Ryan Swaine

19/May/2026 Ryan Swaine

Ultramax sn. JK62411019. Giving a reading of 97.9 during calibration verification procedure, should be 98.5 or above.
Upon return, please run calibration procedure and compare results. Device in warranty, sold October 2025

03/Aug/2026 Robert Connor

Received 2 x Ultramaxo2, s/n JK62411019, LJ06211049, with 2 x blue silicone cover and 1 x silicone tubing, batteries included.

04/Aug/2026 Philip Crossley

Rs has emailed them, they are on holiday. I will keep testing them. 10/Aug/2026 Catherine Spence
engineers room

12/Aug/2026 Philip Crossley

I have spoken to RS and he suggests we return them as they appear to be working fine. I have tested them many times over the past week and they never read low in oxygen. 17/Aug/2026 Catherine Spence
to generate paperwork

Ready For quote

Repair Complete Signed

C. GNEON 19.8.26

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38976	Oxygen Analyser	0111265	JK62411019	Yes
SRN38978	Oxygen Analyser	0111265	LJ06211049	Yes

0140050 x 2 FOC
S/N, SES, SRN

UPS x 1 FOC