

Service Repair Sheet SRS67484

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Misba Suhail

Company/ Hospital Name

Luton & Dunstable Hospital

Department

Clinical Engineering

Position

Clinical Engineer

Direct Phone

01582 491 166 Ext 2535

General Phone

08451 270 127

Opera Account

00003490

Email

Misba.Suhail@ldh.nhs.uk

Order Number

Date Received

21/May/2020

Booked in By

Catherine Spence

Main Company

Viamed

Type Return

Quote

Notes 11/May/2020 Steve Hardaker

11/May/2020 Steve Hardaker

11/May/2020 Steve Hardaker

Sending back a VM-2500-S, serial no: 80640160. He says the SpO2 isn't working. Out of warranty, please quote for repair.

21/May/2020 Catherine Spence

received in, unit rattles

Ready For quote

CGneon 28.5.2020

Repair Complete Signed

---

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN32453	Capnograph	4410520	80640160	N

4440000 x 0.5 hour @ £90 = £45  
SRN, SRS, SRN

4430200 x 1 @ £12.50  
SRS, SRN

4430201 x 1  
SRS, SRN

4430061 x 1 £8.00  
SRS, SRN

UPS x 1 @ £10.

The Luton and Dunstable University Hospital NHS Trust  
Lewsey Road  
Luton  
Bedfordshire  
LU4 0DZ

Telephone : 08451270127 ext. 2480  
Facsimile : 01582570606

## CLINICAL ENGINEERING FAULT REPORT

TO : VIAMED

*REF(SRS67484)*

From : Misba Hu  
Suhail  
Clinical Engineer

*misba.suhail@ldh.nhs.uk*

The following equipment has been taken out of service.

If you have any questions or concerns please contact Misba Hu Suhail on ext. 2480

**Date**

: 11/05/2020

**Asset no**

: 25310

**WR no**

: 92230

**Make / Description of Equipment**

: VIAMED / Capnograph and  
Oximeter

**Model**

: VM-2500-S

**Serial No**

: 80640160

**Fault** : \*SPo2 not working,  
missing screws and screw lock,  
Annual service