

Service Repair Sheet SRS67525

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Hugo Silva

Company/ Hospital Name

Royal Stoke University Hospital

Department

Position

Direct Phone

01782 556936

General Phone

01782 715 444

Opera Account

00012132

Email

hugo.silva@uhnms.nhs.uk

Order Number

Date Received

27/Jun/2020

Booked in By

Catherine Spence

Main Company

Viamed

Type Return

Warranty

Notes 23/Jun/2020 Zoey Teal

23/Jun/2020 Zoey Teal

Sending back two pairs of faulty sensors.

V106119/V106093 from IN165372 under warranty.

Pair V105743/V105744 ran out in May.

23/Jun/2020 Zoey Teal

23/Jun/2020 Sending back two pairs of faulty sensors.

V106119/V106093 from IN165372 under warranty.

Pair V105743/V105744 ran out in May.

Customer is now only sending back the pair which are in warranty.

27/Jun/2020 Catherine Spence

Received S/N V106119/V106093

Ready For quote

Repair Complete Signed

CC, Noun 10.7.2020

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN32895	Oxygen Sensor	0110043	V106093/V106119	Yes

0140013 x 1 EO

old S/N, SRS, SEN

0110043 x 1 EO

new S/N, SRS, SEN

UPS x 1 EO.

Enquiries to: HUGO CAMPOS DA SILVA

Our Ref: /821359

23 June 2020

VIAMED
15 STATION ROAD
CROSS HILLS
KEIGHLEY
WEST YORKSHIRE
BD20 7DT

Dear Sir/Madam,

Please find enclosed the following equipment

Manufacturer: VIAMED
Model:
Serial Number:
Installation Date:
Fault Description: SRS67525 for the cells
- V106119
- V106093

FAO Repair dept

If any chargeable work needs to be undertaken please provide us with a written quote within the next 14 days, prior to any remedial work taking place.

Thank you for your assistance in this matter.

Yours faithfully



Lisa Nixon
Admin Team Leader