

Service Repair Sheet SRS67538

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Paul Scott

James Cook University Hospital

Medical Engineering Dept.

01642 854931

00003709

paul.scottb@nhs.net

18/Jul/2020

Catherine Spence

Viamed

Quote

Notes 13/Jul/2020 Kate Griffiths

13/Jul/2020 Kate Griffiths

Customer would like to send in "TT480 Tom Thumb, when the previous repair was carried out the copper washer is so compressed into the body that I am unable to remove it, without fear of damage to the inside of the body. Is a repair service available or a replacement body" S/N: 040342. SH gave customer option of sending it in or buying block and washer to repair themselves. Customer chose repair by us.

18/Jul/2020 Catherine Spence

received in s/n 040342

O/N: STS1000012136

Ready For quote

CGreen 23-7-2020

Repair Complete Signed

CGreen 27-7-2020

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN32948	Tom Thumb	0310030	040342	N

0340000 @ 0.25 @ £90 = £22.50
S/N, SRS, SRN

0330212 x 1 @ £1.50
SRS, SRN

UPS x 1 £10