

Service Repair Sheet SRS67566

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Chris Millard

Young Calibration Ltd

01273 455572 ext 211

00012389

CM@youngcalibration.co.uk

01/Sep/2020

Robert Connor

Viamed

Warranty

Notes 18/Aug/2020 Zoey Teal

18/Aug/2020 Zoey Teal

Sending in a faulty T-7 sensor.

Serial number - 498824

01/Sep/2020 Robert Connor

1 x T-7 s/n 498824

Ready For quote

Repair Complete Signed

CGreen 12-9-2020

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33094	Oxygen Sensor	0110057	498824	Yes

0140011 x 1 @ £0
S/N, SRS, SRN
No fault found

UPS x 1 @ £0

No
18/
Ser
Sen
01/5
1 x 1

Re

Rep

0140
S/N, E
No fault found

UPS x 1 @ £0

Please find enclosed the faulty O₂ Sensor as discussed with Zoey Teal

Return no. SRS67566

Young
calibration

YOUNG CALIBRATION LIMITED

YOUNG CALIBRATION LABORATORIES

Head Office & Calibration Laboratories
5, Cecil Pashley Way, Shoreham Airport,
Shoreham-by-Sea, West Sussex, BN43 5FF, UK.

Cleanroom & Testing Facilities
Unit 4, Ham Business Centre, Brighton Road,
Shoreham-by-Sea, West Sussex, BN43 6PE, UK.

Telephone: +44 (0) 1273 455572
Email: enquiries@youngcalibration.co.uk
www.youngcalibration.co.uk



ate Promised to Return: 01 Jan 1970 -3600
Millard
Calibration Ltd

55572 ext 211

9

ngcalibration.co.uk

20

1nor

with compliments

12-9-2020

al Number	Warranty
24	Yes