



Sarah Walton <viamed.sarah.walton@gmail.com>

SRS67583 oxygen sensor returns status

1 message

Steve Nixon <office@viamed.co.uk>

29 September 2020 at 10:45

Reply-To: steve.nixon@vandagraphst.com

To: Jim McKay <J.McKay@jfdglobal.com>

Cc: Shaun McGarva <S.McGarva@jfdglobal.com>, Duncan Clark <D.Clark@jfdglobal.com>, Sarah Walton <sarah.walton@vandagraphst.com>

Good morning

The status of the oxygen sensor returns is as follows:

We will generate a FOC order to cover the following 3 sensors:

SRS67583JFD returned 3 sensors to VST 11th September

SN	SRS	SRN	
101358	SRS67583	SRN33111	Out of warranty, but to be replaced as good-will gesture
101494	SRS67583	SRN33112	To be replaced
101646	SRS67583	SRN33113	To be replaced

Regards

--

Steve

Steve Nixon

Director - Vandagraph Sensor Technologies Ltd.

Office: +44 (0)1535 634900

Mobile: +44 (0)7850 252267