

Service Repair Sheet 67495
Contact Name Tracy Wang
Company/ Hospital Name Justec Shenzhen Co. Ltd
General Phone 0086 755 2606 8931
Opera Account 00006027
Email tracy.wang@justec.cn
Date Received 27/Jun/2020
Booked in By Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32896	0110017	416898	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

10.5 in air and 50.9 in oxygen, nonlinear so replaced under warranty with S/N 509981

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32897	0110017	416866	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

9.4 in air and unstable in oxygen, so replaced under warranty with S/N 509982

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32898	0110017	416849	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

Has a bad connector, replaced under warranty with S/N 509983

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32899	0110017	416842	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

11.0 in air and 51.6 in oxygen, nonlinear so replaced under warranty with S/N 509984

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32900	0110017	416873	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

11.1 in air and 51.5 in oxygen, nonlinear so replaced under warranty with S/N 509985

Service Repair Sheet 67495
Contact Name Tracy Wang
Company/ Hospital Name Justec Shenzhen Co. Ltd
General Phone 0086 755 2606 8931
Opera Account 00006027
Email tracy.wang@justec.cn
Date Received 27/Jun/2020
Booked in By Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32901	0110017	416838	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

10.8 in air and 50.9 in oxygen, nonlinear so replaced under warranty with S/N 509986

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32902	0110017	416595	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

118.2 in air, high so replaced under warranty with S/N 509987

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32903	0110017	416843	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

10.7 in air and 51.0 in oxygen, nonlinear so replaced under warranty with S/N 509988

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32904	0110017	416977	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

10.4 in air and 48.3 in oxygen, nonlinear so replaced under warranty with S/N 509989

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32905	0110017	419947	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

8.2 in air and 38.7 in oxygen, nonlinear so replaced under warranty with S/N 509990

Service Repair Sheet 67495
Contact Name Tracy Wang
Company/ Hospital Name Justec Shenzhen Co. Ltd
General Phone 0086 755 2606 8931
Opera Account 00006027
Email tracy.wang@justec.cn
Date Received 27/Jun/2020
Booked in By Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32906	0110017	417183	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

10.4 in air and 48.9 in oxygen, nonlinear so replaced under warranty with S/N 509991

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32907	0110017	416976	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

11.4 in air and unstable in oxygen, unstable so replaced under warranty with S/N 509992

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32908	0110017	417189	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

Bad connector so replaced under warranty with S/N 509993

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32909	0110017	419893	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

8.0 in air and 37.2 in oxygen, nonlinear so replaced under warranty with S/N 509994

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32910	0110017	416712	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

8.3 in air and 39.0 in oxygen, nonlinear so replaced under warranty with S/N 509995

Service Repair Sheet 67495
Contact Name Tracy Wang
Company/ Hospital Name Justec Shenzhen Co. Ltd
General Phone 0086 755 2606 8931
Opera Account 00006027
Email tracy.wang@justec.cn
Date Received 27/Jun/2020
Booked in By Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32911	0110017	416613	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

Bad connector so replaced under warranty with S/N 509996

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32912	0110017	417002	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

11.2 in air and 52.5 in oxygen, nonlinear so replaced under warranty with S/N 509997

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN32913	0110017	416791	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

Bad connector so replaced under warranty with S/N 509998
