

Not on quote
List

Service Repair Sheet SRS67466

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Daniel Webb

Company/ Hospital Name

Luton & Dunstable Hospital

Department

Clinical Engineering

Position

- FBA

Direct Phone

01582 570606 ext 2480

General Phone

08451 270 127

Opera Account

00003490

Email

Order Number

Date Received

28/May/2020

Booked in By

Catherine Spence

Main Company

Viamed

Type Return

Quote

with

Bluepoint

Medical.

for repair

cg 12-9-2020

Notes 30/Mar/2020 Zoey Teal

30/Mar/2020 Zoey Teal

Sending in a VM2500-S. When a sample line is connected, the connection LED turns red after about 8 secs. There is no CO2 values displayed when a 5% CO2 is fed into the device or when one exhales into the sample line. Serial number: 60540154

28/May/2020 Catherine Spence

Unit only sent in

Ready For quote

CGreen 7-9-2020

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN32466	Capnograph	4410520	60540154	N

44400000 x 1 @ £9.15 hr charge for 15 mins of time
S/N, SRS, SRN

4420504 x 1 £1,047.75
SRS, SRN

6 PPOPS1 x 1 @ £10

* 44400000 x 1
S/N, SRS, SRN FOC

* UPS x 1 FOC

* Declined. Sent back
FOC and state
un-repaired as
requested by customer.
cg 10/10/2020

Not on quote
List

Service Repair Sheet SRS67466

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Daniel Webb

Company/ Hospital Name

Luton & Dunstable Hospital

Department

Clinical Engineering

Position

- PPA

Direct Phone

01582 570606 ext 2480

General Phone

08451 270 127

Opera Account

00003490

Email

Order Number

Date Received

28/May/2020

Booked in By

Catherine Spence

Main Company

Viamed

Type Return

Quote

with
Bluepoint
Medical.
for repair
cg 12-9-2020

Notes 30/Mar/2020 Zoey Teal

30/Mar/2020 Zoey Teal

Sending in a VM2500-S. When a sample line is connected, the connection LED turns red after about 8 secs. There is no CO2 values displayed when a 5% CO2 is fed into the device or when one exhales into the sample line. Serial number: 60540154

28/May/2020 Catherine Spence

Unit only sent in

Ready For quote

CGreen 7-9-2020

Repair Complete Signed

CGreen 11-10-2020

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN32466	Capnograph	4410520	60540154	N

44400000 x 1 @ ~~Eg~~ charge for 15 mins of time
S/N, SRS, SRN

4420504 x 1 E1,049.75
SRS, SRN

EG PPOPS1 x 1 @ ~~Eg~~

* 44400000 x 1
S/N, SRS, SRN FOC

* UPS x 1 FOC

* Declined. Sent back
FOC and state
un-repaired as
requested by customer.
cg 10-10-2020

The Luton and Dunstable University Hospital NHS Trust
Lewsey Road
Luton
Bedfordshire
LU4 0DZ

Telephone : 08451270127 ext. 2480
Facsimile : 01582570606

CLINICAL ENGINEERING FAULT REPORT

TO : VIAMED

From : Daniel Webb
Clinical Engineer

02

The following equipment has been taken out of service.

If you have any questions or concerns please contact Daniel Webb on ext. 2480

Date

: 31/03/2020

Asset no

: 21460

WR no

: 94860

Make / Description of Equipment

: VIAMED / Capnograph and
Oximeter

Model

: VM-2500-S

Serial No

: 60540154

Fault : *Capnography not
working.