

Service Repair Sheet 67593

Contact Name	Pier Carla Silvagna
Company/ Hospital Name	DAOS srl
Department	Purchasing
Opera Account	00007385
Email	piercarla.silvagna@daosgroup.it
Date Received	28/Sep/2020
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33127	0110132	376016	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110132 Oxygen sensor - Automotive R-22AV

6.7 in air and 10.8 in oxygen, this sensor is low and replaced under warranty with S/N 526688

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33128	0110081	500895	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Cannot test, replaced under warranty with S/N 528270

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33129	0110017	479763	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

Dead, replaced under warranty with S/N 522909