

Service Repair Sheet 67558

Contact Name	Tracy Wang
Company/ Hospital Name	Justec Shenzhen Co. Ltd
General Phone	0086 755 2606 8931
Opera Account	00006027
Email	tracy.wang@justec.cn
Date Received	01/Sep/2020
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33023	0110023	V120668	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110023 Oxygen sensor R-23V

8.6 in air and 88.6 in oxygen but the sensor is a little erratic, replaced under warranty with S/N V120951

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33024	0110023	V120669	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110023 Oxygen sensor R-23V

20.4 in air and 94.6 in oxygen but the sensor is a little high, replaced under warranty with S/N V120952
