

Service Repair Sheet SRS67626

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Misba Suhail

Company/ Hospital Name

Luton & Dunstable Hospital

Department

Clinical Engineering

Position

Clinical Engineer

Direct Phone

01582 491 166 Ext 2535

General Phone

08451 270 127

Opera Account

00003490

Email

Misba.Suhail@ldh.nhs.uk

Order Number

Date Received

28/Oct/2020

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

Notes 26/Oct/2020 Zoey Teal

26/Oct/2020 Zoey Teal

Sending in a VM2500-S. When a sample line is connected, the connection LED turns red after about 8 secs. There is no CO2 values displayed when a 5% CO2 is fed into the device or when one exhales into the sample line. Serial number: 60540154. They would also like a This was already sent in before on SRS67466 but they requested for us to send it back unrepai red. Will need another quote producing when engineer has inspected the device.

28/Oct/2020 Robert Connor

1 x VM2500S s/n 60540154, with silicone cover and 4 x AA battery

Ready For quote

Connor 2.11.2020

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33231	Capnograph	4410520	60540154	

As per quote from 7-9-2020. QVM125834.

4440000 x 1 @ £90 Per ^{hr} - charge for 15 mins of time
SIN, SRS, SEN

4420504 x 1 @ £1,049.75
SRS, SEN

PPUPS x 1 @ £10.

The Luton and Dunstable University Hospital NHS Trust
Lewsey Road
Luton
Bedfordshire
LU4 0DZ

Telephone : 01582497032
Facsimile : 01582570606

CLINICAL ENGINEERING FAULT REPORT

TO : VIAMED

From : Sean Bunn

The following equipment has been taken out of service.

If you have any questions or concerns please contact Sean Bunn on
01582497032

Date
: 26/10/2020

Asset no
: 21460

WR no
: 94860

Make / Description of Equipment
: VIAMED / Capnograph and
Oximeter

Model
: VM-2500-S

Serial No
: 60540154

Fault : *Saying "sample line
blocked"