



DB200381 x3



Jim McKay J.McKay@jfdglobal.com <u>via</u> gmail.com to steve.nixon@vandagraphst.com, Jamie

Afternoon Steve,

We have a further three faulty Oxygen Cells, from yourselves. The serial numbers are:-

101358, slow reacting and will not calibrate.

101494, failed with no output.

101646, failed with no output.

I will have these units boxed up and returned to yourselves for further investigation. Please forward any internal investigation findings and corrective actions to myself or Jim McKay. I appreciate your assistance with

Regards, Jamie Tough.

Jamie Tough Quality Inspector



JFD

J.Tough@jfdglobal.com

Office: +44 (0)1224 740145 / Fax: +44 (0)1224 740172

Enterprise Drive, Westhill, AB32 6TQ

United Kingdom jfdglobal.com

Follow us on:









