



SRS67583 oxygen sensor returns status



Steve Nixon <steve.nixon@vandagraphst.com>
to Jim, Shaun, Duncan, Sarah

Good morning

The status of the oxygen sensor returns is as follows:

We will generate a FOC order to cover the following 3 sensors:

SRS67583

JFD returned 3 sensors to VST 11th September

SN	SRS	SRN	
101358	SRS67583	SRN33111	Out of warranty, but to be replaced as good-will gesture
101494	SRS67583	SRN33112	To be replaced
101646	SRS67583	SRN33113	To be replaced

Regards
--

Steve

Steve Nixon
Director - Vandagraph Sensor Technologies Ltd.

Office: +44 (0)1535 634900
Mobile: +44 (0)7850 252267

Reply

Reply to all

Forward