

Service Repair Sheet SRS67632

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Saeed Namini

Company/ Hospital Name

St James University Hospital

Department

Medical Electronics

Position

Medical Electronics Technician

Direct Phone

0113 206 4829

General Phone

0113 243 3144

Opera Account

00002570

Email

Saeed.Namini@nhs.net

Order Number

Date Received

02/Nov/2020

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes 02/Nov/2020 Robert Connor

02/Nov/2020 Robert Connor

Returning 1 x 0110420

02/Nov/2020 Robert Connor

1 x 0110420 s/n EJ35601069, will not calibrate at 100% O2.

Ready For quote

Repair Complete Signed

CCNEON 4-11-2020

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33241	Oxygen Sensor	0110420	EJ35601069	Yes

0140013 x 1 FOC
Old S/N, SRS, SRN

0110420 x 1 FOC
New S/N, SRS, SRN

UPS 1 @ £10

REJECT NOTE

ISSUE 2.0 (8-MAR-2018)

Date 28/10/2020

Reference number: REJ_052

Goods Supplier:

Viamed Ltd
15 Station Road
Cross Hills
Keighley
BD20 7DT

Correspondence Address:

St James's Hospital
Leeds Teaching Hospitals NHS Trust
Lincoln Wing
Leeds
LS9 7TF8N

This is to advise that the following goods/services have failed to meet our quality standards. Please pass this form to your Quality Manager for further processing.

Content description			
O2 cell Part No: 0110420 s/n: EJ35601069			
Description of problem identified			
Will not calibrate to 100% Oxygen			
Ordered by	Leeds Teaching Hospitals NHS Trust		
Order number	RR8N400085093	Delivery reference	
Date received		Reject raised by	Saeed. Namini
Contact email	Saeed.Namini@nhs.net	Contact Number	01132064829

The goods have been:

- ☒ returned to the supplier
☐ retained on the instructions of the supplier
☐ referred to supplier, and shortfall is awaited
☐ used on concession
☐ repaired by Medical Physics
☐ scrapped by Medical Physics

Returns No _____

Contact name _____

Concession note number _____

Comments			
Completed satisfactorily		Date	
Signed off by		Position	