

Service Repair Sheet SRS67619

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Magnus Persson

Company/ Hospital Name

Swevet - AB

Department

Position

Direct Phone

46 416 258 21

General Phone

46 771215500

Opera Account

00006308

Email

magnus.persson@swevet.se

Order Number

Date Received

28/Oct/2020

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

service

Notes 20/Oct/2020 Zoey Teal

20/Oct/2020 Zoey Teal

Sending in a AX300-I. Serial number - 328347.

They would like it servicing. When the device is on the screen flashes sensor and 0.00. They can not calibrate it.

28/Oct/2020 Robert Connor

1 x AX300 s/n 328347, with base stand, cable s/n 0013869, R-17MED s/n 135326, and 3 x AA battery

Ready For quote

CGneen 5-11-2020

Repair Complete Signed

CGneen 20-11-2020

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33232	Oxygen Monitor	0111230	328347	N
SRN33233	Oxygen Monitor Cable	0131202	0013869	N
SRN33234	Oxygen Sensor	0110017	135326	N

01800004 x 1 € 37.75.
S/N, SRS, SRN

0140013 x 1 - should be 0140012.
old S/N, SRS, SRN

0110017 x 1 ~~€ 42.00~~ € 32.00
SR SRS, SRN.

UPS x

~~32x24x15cm~~

32x24x15cm. 32x24x16cm

~~32x24x12cm~~

€ 23.51

- need to change CG 21-11-2020
000
0140025
SRS 33233
SRN 67619
S/N 0013869