Service Repair Sheet 67646

Contact Name Company/ Hospital Name

General Phone

Email

**Date Received** Booked in By

Alan Cook

V-Tech UK Ltd

0208 498 1288

Alan@v-techuk.com

29/Nov/2020

Catherine Spence

**Equipment Type Under Warranty** Repair Ref S/N

SRN33251 0110122 413855 Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1 0110122 Oxygen sensor - Automotive R-22A

11.4 in air and 55.3 in oxygen, this sensor is nonlinear and replaced under warranty with S/N 554655

S/N **Equipment Type Under Warranty** Repair Ref

SRN33252 0110122 413860 Oxygen Sensor No Fault Found Time: 0 Hour(s)

12.1 in air and 58.2 in oxygen this sensor is no fault found.