

Service Repair Sheet 67627

Contact Name	Sudath Weeraman
Company/ Hospital Name	Prime Lanka
General Phone	+94 1071 8732 285
Opera Account	00006714
Email	sudathweeraman17@gmail.com
Date Received	11/Jan/2021
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33328	0110429	FG40399016	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429 Oxygen sensor MAX-250E

Reading low in oxygen. Replaced under warranty with S/N FH89999087
