

Service Repair Sheet SRS67626

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Misba Suhail

Luton & Dunstable Hospital

Clinical Engineering

Clinical Engineer

01582 491 166 Ext 2535

08451 270 127

00003490

Misba.Suhail@ldh.nhs.uk

28/Oct/2020

Robert Connor

Viamed

Quote

RMA request
sent to bluepoint
cg 10-11-2020

Notes 26/Oct/2020 Zoey Teal

26/Oct/2020 Zoey Teal

Sending in a VM2500-S. When a sample line is connected, the connection LED turns red after about 8 secs. There is no CO2 values displayed when a 5% CO2 is fed into the device or when one exhales into the sample line. Serial number: 60540154. They would also like a This was already sent in before on SRS67466 but they requested for us to send it back unrepaired. Will need another quote producing when engineer has inspected the device.

28/Oct/2020 Robert Connor

1 x VM2500S s/n 60540154, with silicone cover and 4 x AA battery

Ready For quote

CGreen 2.11.2020

Repair Complete Signed

CGreen 18.1.2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33231	Capnograph	4410520	60540154	N

As per quote from 7-9-2020. QV!M125834.

4440000 x 1 @ £90 ^{hr} Ret ~~etc~~ - charge for 15 mins of time
S/N, SRS, SRN

4420504 x 1 £1,049.75
SRS, SRN

PPUPS x 1 @ £10.

The Luton and Dunstable University Hospital NHS Trust
Lewsey Road
Luton
Bedfordshire
LU4 0DZ

Telephone : 01582497032
Facsimile : 01582570606

CLINICAL ENGINEERING FAULT REPORT

TO : VIAMED

From : Sean Bunn

The following equipment has been taken out of service.

If you have any questions or concerns please contact Sean Bunn on
01582497032

Date

: 26/10/2020

Asset no

: 21460

WR no

: 94860

Make / Description of Equipment

: VIAMED / Capnograph and
Oximeter

Model

: VM-2500-S

Serial No

: 60540154

Fault : *Saying "sample line
blocked"