

Service Repair Sheet SRS67688

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Matthew Anderson

Company/ Hospital Name

Chelsea & Westminster Hospital

Department

Clinical Engineering

Position

Direct Phone

020 3315 8103

General Phone

Opera Account

00002824

Email

matthew.anderson@chelwest.nhs.uk

Order Number

Date Received

11/Jan/2021

Booked in By

Catherine Spence

Main Company

Viamed

Type Return

Warranty

Notes 31/Dec/2020 Kate Griffiths

31/Dec/2020 Kate Griffiths

Faulty MaxO2 ME cable. Customer says "We have found that one of the cables has failed. It is intermittently working when the cable is wiggled. Would it be possible to arrange a warranty replacement cable?" s/n FJ31899018. Cathy confirmed customer needs to send back monitor and cable. Customer aware.

11/Jan/2021 Catherine Spence

received in unit cable and oxygen sensor (FJ78999028)

Ready For quote

Repair Complete Signed

C Green 19-1-2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33325	Oxygen Monitor	0111263	FJ31899018	Yes
SRN33326	Oxygen Monitor Cable	0131700	Tracking17	Yes
SRN33327	Oxygen Sensor	0110452	FJ78999028	Yes

* 0140000 - please change to: cg 21-1-2021
1416000 x 1 FOC
S/N, SRS, SRN no fault found.

0140025 x 1 x FOC
old S/N, SRS, SRN

0131700 x 1 x FOC
new S/N, SRS, SRN. Warranty Replacement

0140011 x 1 FOC
S/N, SRS, SRN no fault found

UPS x 1 FOC