

Service Repair Sheet 67684

Contact Name	David Blackwell
Company/ Hospital Name	Darent Valley Hospital
Department	EME Department
Position	Electro Bio Medical Engineering Technician
General Phone	01322 42 81 00
Opera Account	00001365
Email	david.blackwell@dvh.nhs.uk
Date Received	11/Jan/2021
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33330	0110435	FJ83699235	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110435 Oxygen sensor MAX-250TM

9.4 in air and 43.3 in oxygen. This sensor is nonlinear and replaced under warranty with S/N FJ83699241

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33331	0110435	FJ83699240	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110435 Oxygen sensor MAX-250TM

9.9 in air and 45.0 in oxygen. This sensor is nonlinear and replaced under warranty with S/N FJ83699242
