

Service Repair Sheet 67668

| | |
|------------------------|---------------------------------------|
| Contact Name | Lewis Ball |
| Company/ Hospital Name | Inspiration Healthcare Ltd |
| Department | Service Department |
| Position | Senior Service Engineer |
| Direct Phone | 07584 147057 |
| General Phone | 01455 840555 |
| Opera Account | 00012240 |
| Email | lewis.ball@inspiration-healthcare.com |
| Date Received | 22/Jan/2021 |
| Booked in By | Catherine Spence |

| | | | | |
|----------|---------|---------|----------------|----------------|
| Repair | Ref | S/N | Equipment Type | Under Warranty |
| SRN33340 | 0110047 | V104325 | Oxygen Sensor | |

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110047 Oxygen sensor R-47V

12.0/12.1 in air and 57.5/58.4 in oxygen but has intermittent high output. Replaced under warranty with S/N V104964
