Service Repair Sheet SRS67691

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Alan Marples

Chesterfield Royal Hospital

Department of Clinical Engineering

Specialist Clinical Engineer

01246 513065

01246 277 271

00001170

alanmarples@nhs.net

27/Jan/2021

Catherine Spence

Viamed

Warranty

Notes 08/Jan/2021 Steve Hardaker

08/Jan/2021 Steve Hardaker

08/Jan/2021 Steve Hardaker

Faulty R-17MED sensor, only just received with one of the 5 MX300s supplied on RVM127968-1 on 23/12/21.

Have requested serial number, will add if/when provided.

19/Jan/2021 Steve Hardaker

Not yet received, chased.

27/Jan/2021 Catherine Spence

1 x R17Med S/N 565706

when connected to MX the devices alarm sensor and will not calibrate

Ready For quote

Repair Complete Signed

<u>CONOON 1-2-70</u>21

4

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33353	Oxygen Sensor	0110017	565706	Yes

0140013 ×1 0 60 SIN, SES, SPN

OLICOLT XI Q EO NEW S/N, SPS, SPN

UPS x1 @ EO.



Derbyshire Support and Facilities Services

Chesterfield Royal Hospital, Calow, Chesterfield, Derbyshire S44 58L

## **Clinical Engineering Department**

Telephone: 01246 512058

Fax: 01246 512631

e-mail: alanmarples@nhs.net

Ref: AM/AM/120121

12th January 2021

Returns Department Viamed 15 Station Road Cross Hills Keighley West Yorkshire BD20 7DT Sold 23-12-2020 EVM127968-1

Ref: SRS67691

Dear Sir/Madam,

Please find enclosed for repair evaluation:

1 x R-17MED Oxygen Sensor

When devices have this cell connected (supplied with an MX-300i oxygen analyser) the devices alarm 'Sensor' and will not calibrate.

Thanking you in advance.

Yours faithfully

Alan Marples EngTech MIET RCT Specialist Clinical Engineer