Service Repair Sheet 67685

Contact Name Company/ Hospital Name General Phone

Viobreath S.A. +302510620770 Opera Account 00006486 **Date Received** 22/Jan/2021

Nikolaos

**Under Warranty** 

Repair Ref S/N **Equipment Type** SRN33342 0111265 FB59311016 Oxygen Analyser

Time: 0 Hour(s)

Parts Replaced

Booked in By

Qty: 1 0111265 Oxygen analyser Ultramax

Catherine Spence

The Ultramax Oxygen monitor has been replaced under warranty with SN:FE85711006.

S/N **Equipment Type Under Warranty** Repair Ref

SRN33343 0111265 CC35011002 Oxygen Analyser

Time: 0 Hour(s)

Parts Replaced

Qty: 1 0111265 Oxygen analyser Ultramax

The Ultramax Oxygen monitor has been replaced under warranty with SN:FE85711005.