

Service Repair Sheet 67707

| | |
|------------------------|--|
| Contact Name | Rennie Saverton |
| Company/ Hospital Name | Inspiration Healthcare Ltd |
| Position | Field Service Engineer |
| General Phone | 01455 840555 |
| Opera Account | 00012240 |
| Email | Rennie.Saverton@inspiration-healthcare.com |
| Date Received | 03/Feb/2021 |
| Booked in By | Catherine Spence |

| | | | | |
|----------|---------|---------|----------------|----------------|
| Repair | Ref | S/N | Equipment Type | Under Warranty |
| SRN33368 | 0110047 | V104251 | Oxygen Sensor | |

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110047 Oxygen sensor R-47V

The R-47V Oxygen sensor has been replaced under warranty with SN:V104968

| | | | | |
|----------|---------|---------|----------------|----------------|
| Repair | Ref | S/N | Equipment Type | Under Warranty |
| SRN33369 | 0110047 | V104575 | Oxygen Sensor | |

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110047 Oxygen sensor R-47V

The R-47V Oxygen sensor has been replaced under warranty with SN:V104969.

| | | | | |
|----------|---------|---------|----------------|----------------|
| Repair | Ref | S/N | Equipment Type | Under Warranty |
| SRN33370 | 0110047 | V104578 | Oxygen Sensor | |

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110047 Oxygen sensor R-47V

The R-47V Oxygen sensor has been replaced under warranty with SN:V104970.

| | | | | |
|----------|---------|---------|----------------|----------------|
| Repair | Ref | S/N | Equipment Type | Under Warranty |
| SRN33372 | 0110021 | V114652 | Oxygen Sensor | |

No Fault Found
Time :0 Hour(s)The R-22MEDV Oxygen sensor has been tested. No fault was found.
