

Service Repair Sheet 67717

Contact Name	Pegah Monem
Company/ Hospital Name	Royal National Orthopaedic Hospital
General Phone	0208 9095694
Opera Account	00004860
Email	pegah.monem@althea-group.com
Date Received	09/Feb/2021
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33381	0110023	V121272	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110023 Oxygen sensor R-23V

0/0 in air. Replaced under warranty with S/N V121350

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33382	0110023	V121274	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110023 Oxygen sensor R-23V

0/18.0 in air, has an intermittent fault. Replaced under warranty with S/N V121493
