



Warning No company id linked:

Enter CID Number

Link Company ID

SRS67651

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

ADD
DOCUMENT
TO SRS :
Document
Description

Choose a file to upload: No file chosen

Choose file

No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System. - will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 67651		Notes
Company / Hospital	JFD	24/Nov/2020 Steve Nixon
Contact Name	Duncan Clark	24/Nov/2020 Steve Nixon
Department		24/Nov/2020 Steve Nixon
Position		
Company Phone	01224 740145	Returning for assessment only, discuss with SN:
Direct Phone		SN:101852 – Failed Mag Range (47+ Nt).
Opera Account	VST036	SN:101872 – Failed Mag Range (44+ Nt).
Email		SN:101882 – Failed Mag Range (104 Nt).
Order Number		SN:101886 – Failed Mag Range (51+ Nt)
Viamed ORD Number		29/Nov/2020 Catherine Spence
Date Received Into building	29 Nov 2020	received in s/n 101902,101886,101852,101882,101872
Type	Warranty	18/Jan/2021 Catherine Spence
Issues?	212179	engineers room
		LINKED ISSUE NOTES:
		212179 :
		AutoGenerated Issue SRS67651 Appears to be Complete
		01 Feb 2021 Catherine Spence
		noted

Items for Repair

SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN33254	Oxygen Sensor	8010050	1642441	101882	Oxygen Sensor -	Yes	No	On Hold	High magnetic	00:00

	VST				JFD				signature	
SRN33257	Oxygen Sensor VST	8010050	1640800	101872	Oxygen Sensor - JFD	Yes	No	On Hold	High magnetic signature	00:00
SRN33257 Customer Notes: Failed Mag Range (44+ Nt)										
SRN33256	Oxygen Sensor VST	8010050	1640780	101852	Oxygen Sensor - JFD	Yes	No	On Hold	High magnetic signature	00:00
SRN33256 Customer Notes: Failed Mag Range (47+ Nt)										
SRN33258	Oxygen Sensor VST	8010050	1642445	101886	Oxygen Sensor - JFD	Yes	No	On Hold	High magnetic signature	00:00
SRN33258 Customer Notes: Failed Mag Range (51+ Nt)										
SRN33259	Oxygen Sensor VST	8010050	1642461	101902	Oxygen Sensor - JFD	Yes	No	On Hold	High magnetic signature	00:00

Currently Viewing ITEM SRN33254 Oxygen Sensor VST 8010050 101902 Oxygen Sensor - JFD

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The JFD Oxygen sensor has been disassembled into component parts for testing.	28/Jan/2021 Michael Green The JFD Oxygen sensor has been disassembled into component parts for testing.	The JFD Oxygen sensor has been disassembled into component parts for testing.