

Service Repair Sheet 67651

Contact Name	Duncan Clark
Company/ Hospital Name	JFD
General Phone	01224 740145
Opera Account	VST036
Date Received	29/Nov/2020
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	On Hold	Under Warranty
SRN33254	8010050	101882	Oxygen Sensor VST	Time :0 Hour(s)	

The JFD Oxygen sensor has been disassembled into component parts for testing.

Repair	Ref	S/N	Equipment Type	On Hold	Under Warranty
SRN33256	8010050	101852	Oxygen Sensor VST	Time :0 Hour(s)	

The JFD Oxygen sensor has been disassembled into component parts for testing.

Repair	Ref	S/N	Equipment Type	On Hold	Under Warranty
SRN33257	8010050	101872	Oxygen Sensor VST	Time :0 Hour(s)	

The JFD Oxygen sensor has been disassembled into component parts for testing.

Repair	Ref	S/N	Equipment Type	On Hold	Under Warranty
SRN33258	8010050	101886	Oxygen Sensor VST	Time :0 Hour(s)	

The JFD Oxygen sensor has been disassembled into component parts for testing.

Repair	Ref	S/N	Equipment Type	On Hold	Under Warranty
SRN33259	8010050	101902	Oxygen Sensor VST	Time :0 Hour(s)	

The JFD Oxygen sensor has been disassembled into component parts for testing.