



Service Repair Sheet 67650

Contact Name	Duncan Clark
Company/ Hospital Name	JFD
General Phone	01224 740145
Opera Account	VST036
Date Received	29/Nov/2020
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33260	8010050	101600	Oxygen Sensor VST	
Replaced				
Time :0 Hour(s)				

High output - replaced under warranty.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33261	8010050	101409	Oxygen Sensor VST	
Credited				
Time :0 Hour(s)				
