

Service Repair Sheet SRS67719

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Tracey Clamp

Company/ Hospital Name

Royal Derby Hospital

Department

Clinical Engineering

Position

Direct Phone

01332 788031

General Phone

01332 34 01 31

Opera Account

00001390

Email

tracey.clamp@nhs.net

Order Number

Date Received

16/Feb/2021

Booked in By

Catherine Spence

Main Company

Viamed

Type Return

Warranty

Notes 02/Feb/2021 Zoey Teal

02/Feb/2021 Zoey Teal

Sending back two faulty R-17MEDs that are out of the box failures. Serial numbers 411596 and 411597.

16/Feb/2021 Catherine Spence

Received in. Sold 17/04/2020 on RVM123407-1

Ready For quote

Repair Complete Signed

C. Spence 18-2-2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33421	Oxygen Sensor	0110017	411596	Yes
SRN33420	Oxygen Sensor	0110017	411597	Yes

0140013 x 2 @ FCC  
old SN, SRS, SRN

0110017 x 2 @ FCC  
new SN, SRS, SRN

UPS x 1 @ FCC



**University Hospitals of  
Derby and Burton**  
NHS Foundation Trust

Our ref: TLC  
Telephone No. (01332) 788031  
e-mail: tracey.clamp@nhs.net

4<sup>th</sup> February 2021

Viamed Ltd  
15 Station Road  
Cross Hills  
North Yorkshire  
BD20 7DT  
**FAO. Repairs**

**Royal Derby Hospital**  
Uttoxeter Road  
DERBY  
DE22 3NE  
**01332 340131**

Dear Zoe

**Re: Returns No.SRS67719**

Please find enclosed 2 x R-17MED Oxygen Sensors, Serial Nos. 411596 and 411597,  
they are both out of box failures.

The replacement sensors should be sent to:

Clinical Engineering  
Level 1  
Kings Treatment Centre  
Royal Derby Hospital  
Uttoxeter Road  
Derby  
DE22 3NE

Sold 17/4/2020.  
QVM123407-1

Yours sincerely

T L Clamp  
Service Co-Ordinator

**Encs.**

[www.uhdb.nhs.uk](http://www.uhdb.nhs.uk)

Chair: Dr Kathy McLean OBE

Follow us on Twitter @UHDBTrust

Chief Executive: Gavin Boyle

Please visit [www.uhdb.nhs.uk](http://www.uhdb.nhs.uk) for the latest advice on attending our hospitals during **COVID-19**.