Service Repair Sheet 67719

Contact Name

Company/ Hospital Name
Department
Direct Phone
General Phone
Opera Account

Royal Derby Hospital
Clinical Engineering
01332 788031
01332 34 01 31
00001390

Opera Account 00001390 Email tracey.clamp@nhs.net

Date Received 16/Feb/2021
Booked in By Catherine Spence

Repair Ref S/N Equipment Type Under Warranty

SRN33420 0110017 411597 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced
Qty: 1 0110017 Oxygen sensor R-17MED

10.4 in air and 51.3 in oxygen, this sensor is nonlinear Replaced under warranty with S/N 571909

Tracey Clamp

Repair Ref S/N Equipment Type Under Warranty

SRN33421 0110017 411596 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

11.4 in air and 56.7 in oxygen, this sensor is nonlinear Replaced under warranty with S/N 571908