

## Service Repair Sheet SRS67700

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Colin Gregory

Kingston Hospital

ITU

Senior Technician Officer

0208 934 2392

020 85 46 77 11

00002420

04/Feb/2021

Catherine Spence

Viamed

Warranty

Notes 18/Jan/2021 Sophie Lines

20/Jan/2021 Sophie Lines

18/Jan/2021 Sophie Lines

Sending back a Handi analyser - bought 15 recently and 1 unit won't calibrate. FK59399024 - CG going to do them a reutns label as they have requested one. Believe it is under warranty

04/Feb/2021 Catherine Spence

received in

Ready For quote

Repair Complete Signed

CANEON 18.2.2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33373	Oxygen Analyser	0111250	FK59399024	Yes

~~0140050~~

0140050 x 1 @ EO.

S/N, SRS, SRN

0111250 x 1 @ EO

New S/N, SRS, SRN

UPS x 1 @ EO.

Hi all,

As discussed, please find enclosed the Handi+, which I have not been able to calibrate. I did note that the sealing tag on the end of the sensor was missing when I removed the unit from it's plastic bag.

Regards

Colin Gregory

Clinical Engineering Dept

Kingston Hospital NHS Foundation Trust

Kingston

Surrey

KT2 7QB

Tel: 0208934 2392

11-2-2021

Calibration numbers  
not holding.