

Service Repair Sheet SRS67730

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Alex Ferguson

Company/ Hospital Name

Churchill Hospital

Department

Clinical Engineering

Position

Senior Clinical Technologist

Direct Phone

01865 572163

General Phone

01865 572163

Opera Account

00004030

Email

Alex.Ferguson@ouh.nhs.uk

Order Number

Date Received

17/Feb/2021

Booked in By

Catherine Spence

Main Company

Viamed

Type Return

Quote

Notes 11/Feb/2021 Zoey Teal

11/Feb/2021 Zoey Teal

Sending in a DB3. Serial number H0003028. It does not have an output. They have tried a new battery and new patient leads.

17/Feb/2021 Catherine Spence

Include Job Reference 579308 on all paperwork

17/Feb/2021 Catherine Spence

received in microstim S/N H0003028 with leads

Send quote to clinical.engineering@ouh.nhs.uk

Ready For quote

CGNEEN 24-2-2021

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33426	Microstim DB3	2510000	H0003028	N

2540010 x 1 @ £45
S/N, SRS, SRN

UPS x 1 £10.

Repair Quotation Request

Date of request: 11/02/2021



Oxford University Hospitals
NHS Foundation Trust

Post to:

Viamed Limited
15 Station Road
Cross Hills
Keighley
West Yorkshire
BD20 7DT

Deliver To:

Clinical Engineering
Industrial Block
John Radcliffe Hospital
Headley Way
OX3 9DU

Telephone: 01865 221548

Email: Clinical.engineering@ouh.nhs.uk

The following item(s) of equipment are reported faulty and require testing/repair.

Brand: VIAMED

Model: MICROSTIM DB3

Serial No: H0003028

Asset No: 081691

The reported fault is: No output – new battery fitted

Please carry-out an evaluation and forward a quotation to Clinical Engineering at the following address: Clinical.engineering@ouh.nhs.uk

Please include the **Job reference 579308** in all quotes and correspondence related to this request.

Kind regards,

Clinical Engineering

REF: SRS67730