

Service Repair Sheet SRS67740

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Ali Kotadia

Charing Cross Hospital

Clinical Engineering

Team Leader

0203 3111046

00003170

aliakbar.kotadia@nhs.net

05/Mar/2021

Catherine Spence

Viamed

Quote

Notes 24/Feb/2021 Zoey Teal

24/Feb/2021 Zoey Teal

Sending in a faulty DB3. Serial number H0000359.

05/Mar/2021 Catherine Spence

received in with leads and battery  
not working properly

Ready For quote

CGreen 10-8-2021

Repair Complete Signed

---

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33451	Microstim DB3	2510000	H0000359	<u>2</u>

~~#~~ 2540010 x 1 @ £45

SM, SR5, SRN

OPS x 1 @ £10.

**Send Away Repair Form**

**TO:**  
**VIAMED LIMITED**  
FAO REPAIRS  
15 STATION ROAD, CROSS HILLS  
NEAR KEIGHLEY, WEST YORKSHIRE  
BD20 7DT  
+44(0)1535634542

**FROM:** CLINICAL ENGINEERING DEPT  
CHARING CROSS HOSPITAL  
MARGRAVINE ROAD  
LONDON  
W6 8RF  
TELEPHONE: 0203 3111046

Consignment No.: WAYBILL 26 7402 7230

To the Service Department: **REPAIRS****Despatch Date: 24/02/2021**

Type of work:

- ☒ Repair    ☐ Calibration    ☐ Modification    ☐ Warranty    ☐ Recall    ☐ Rework  
☐ Other:

Manufacturer: VIAMED LIMITED

Work Order No.: 145690

Type of Equipment: NERVE STIMULATOR

Model: MICROSTIM DB3

Control Number: 539219

Location: CXH

Serial Number: H0000359

Precise details of fault:

Not working properly (as reported by end user) Ref No: SRS67740

**Please email repair estimates / quotations- [aliakbar.kotadia@nhs.net](mailto:aliakbar.kotadia@nhs.net)**Any enquiries should be made to (name): **ALI KOTADIA**Accessories enclosed: ☐ mains lead    ☐ transducer    ☒ patient lead    ☐ noneOther: **BATTERY****Status of Decontamination**

Our Quality Management System is ISO 9001 registered Certificate No: 11551

*Tick as appropriate*

- ☐ This equipment has been in contact with infectious or potentially infectious material.

It has been decontaminated by the following means:

The following safety precautions are recommended:

- ☒ This equipment is not known to be contaminated

Signed: **AAK**Date: **24/02/2021**Position **TEAM LEAD**