

Service Repair Sheet SRS67781

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Jan Bowen

Huntleigh Healthcare

Diagnostic Products Division

02920 447097

00011875

jan.bowen@arjo.com

26/Mar/2021

Catherine Spence

Viamed

Quote

Notes 25/Mar/2021 Sarah Walton

25/Mar/2021 Sarah Walton

Faulty V1000 unit.

S/N: PR01883A16

26/Mar/2021 Catherine Spence

Received with batteries

It is crackling and very low audio

Ready For quote

CCNen 29.3.2021

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33496	Foetal Simulator	1410000	PR01883A16	N

NOT SURE IF
DISTRIBUTOR.

If so then

£38.25

1480000 x 1 £45 :

S/N, SRS, SRN

1430309 x 1 £0.

SRS, SRN

UPS x 1 £10.

WITH COMPLIMENTS

HUNTLEIGH

Hi,
The Fault with the V1000 Fault Heart Simulator
is that it is crackling and very low Audio.

Regards,
Ian Bowan

Huntleigh Healthcare Ltd • Diagnostic Products Division • 35 Portmannor Road • Cardiff • CF24 5HN • United Kingdom
Tel: +44 (0)29 2048 5885 • Fax: +44 (0)29 2049 2520 • Mail: sales@huntleigh-diagnostics.co.uk
www.huntleigh-diagnostics.com • Registered No: 942245 • Registered Office: 310-312 Dallow Road, Luton, LU1 1TD

AN HUNTLIGH COMPANY
MEMBER OF THE GETTING GROUP