

## Service Repair Sheet 67687

Contact Name	Aleh Satsishur
Company/ Hospital Name	Consumeda UAB
Position	General Manager
Direct Phone	+3725 775 3148
Opera Account	00006262
Email	consumeda3@gmail.com
Date Received	01/Mar/2021
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33437	0110081	479035	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1    0110081    Oxygen sensor    UFO 130-2

Untested, Replaced under warranty with S/N 598558

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33438	0110081	500812	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1    0110081    Oxygen sensor    UFO 130-2

Untested, Replaced under warranty with S/N 598559

Repair	Ref	S/N	Equipment Type	End Of Life
SRN33439	0110081	361224	Oxygen Sensor	Time :0 Hour(s)

Sensor is at the end of its life

Repair	Ref	S/N	Equipment Type	End Of Life
SRN33440	0110081	361235	Oxygen Sensor	Time :0 Hour(s)

Sensor is at the end of its life

Repair	Ref	S/N	Equipment Type	End Of Life
SRN33441	0110081	372461	Oxygen Sensor	Time :0 Hour(s)

Sensor is at the end of its life

## Service Repair Sheet 67687

Contact Name	Aleh Satsishur
Company/ Hospital Name	Consumeda UAB
Position	General Manager
Direct Phone	+3725 775 3148
Opera Account	00006262
Email	consumeda3@gmail.com
Date Received	01/Mar/2021
Booked in By	Catherine Spence

Repair SRN33442	Ref 0110081	S/N 361214	Equipment Type Oxygen Sensor	End Of Life Time :0 Hour(s)
--------------------	----------------	---------------	---------------------------------	--------------------------------

Sensor is at the end of its life

Repair SRN33443	Ref 0110081	S/N 344372	Equipment Type Oxygen Sensor	End Of Life Time :0 Hour(s)
--------------------	----------------	---------------	---------------------------------	--------------------------------

Sensor is at the end of its life

Repair SRN33445	Ref 0110081	S/N 364236	Equipment Type Oxygen Sensor	End Of Life Time :0 Hour(s)
--------------------	----------------	---------------	---------------------------------	--------------------------------

Sensor is at the end of its life

Repair SRN33446	Ref 0110081	S/N 364238	Equipment Type Oxygen Sensor	End Of Life Time :0 Hour(s)
--------------------	----------------	---------------	---------------------------------	--------------------------------

Sensor is at the end of its life

Repair SRN33447	Ref 0110081	S/N 579329	Equipment Type Oxygen Sensor	End Of Life Time :0 Hour(s)
--------------------	----------------	---------------	---------------------------------	--------------------------------

Sensor is at the end of its life

Repair SRN33448	Ref 0110081	S/N 148458	Equipment Type Oxygen Sensor	End Of Life Time :0 Hour(s)
--------------------	----------------	---------------	---------------------------------	--------------------------------

Sensor is at the end of its life

Service Repair Sheet 67687

Contact Name	Aleh Satsishur
Company/ Hospital Name	Consumeda UAB
Position	General Manager
Direct Phone	+3725 775 3148
Opera Account	00006262
Email	consumeda3@gmail.com
Date Received	01/Mar/2021
Booked in By	Catherine Spence

---

Repair	Ref	S/N	Equipment Type	End Of Life
SRN33449	0110081	341430	Oxygen Sensor	Time :0 Hour(s)

Sensor is at the end of its life

---