

Service Repair Sheet SRS67766

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Ryan Curzon

Company/ Hospital Name

Gemco

Department

Position

Direct Phone

General Phone

0844 24 98 102

Opera Account

00020099

Email

Ryan.Curzon@gemco.co.uk

Order Number

Date Received

22/Mar/2021

Booked in By

Catherine Spence

Main Company

Viamed

Type Return

Warranty

Notes 16/Mar/2021 Sophie Lines

16/Mar/2021 Sophie Lines

16/Mar/2021 Sophie Lines

25x faulty sensors to return.

22/Mar/2021 Catherine Spence

13x high Voltage over 13mv

12 x fail to fall to correct level

Ready For quote

Repair Complete Signed

CG Neen 14-4-2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33466	Oxygen Sensor	0110182	V102614	Yes
SRN33467	Oxygen Sensor	0110182	V102556	Yes
SRN33468	Oxygen Sensor	0110182	V102566	
SRN33469	Oxygen Sensor	0110182	V102578	
SRN33470	Oxygen Sensor	0110182	V102587	Yes
SRN33471	Oxygen Sensor	0110182	V102555	
SRN33472	Oxygen Sensor	0110182	V102586	Yes
SRN33473	Oxygen Sensor	0110182	V102609	Yes
SRN33474	Oxygen Sensor	0110182	V102563	Yes
SRN33475	Oxygen Sensor	0110182	V102579	Yes
SRN33476	Oxygen Sensor	0110182	V102606	Yes
SRN33477	Oxygen Sensor	0110182	V102619	Yes
SRN33478	Oxygen Sensor	0110182	V102598	Yes
SRN33479	Oxygen Sensor	0110182	V102574	Yes
SRN33480	Oxygen Sensor	0110182	V102597	Yes
SRN33481	Oxygen Sensor	0110182	V102565	Yes
SRN33482	Oxygen Sensor	0110182	V102607	Yes

0140013 x 25
S/N, SRS, SR0110182 x 2
New S/N, SRS, S

UPS x 100

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33485	Oxygen Sensor	0110182	V102612	Yes
SRN33486	Oxygen Sensor	0110182	V102581	Yes
SRN33487	Oxygen Sensor	0110182	V102620	Yes
SRN33488	Oxygen Sensor	0110182	V102590	Yes
SRN33489	Oxygen Sensor	0110182	V102558	Yes

Service Repair Sheet 67766

Contact Name	Ryan Curzon
Company/ Hospital Name	Gemco
General Phone	0844 24 98 102
Opera Account	00020099
Email	Ryan.Curzon@gemco.co.uk
Date Received	22/Mar/2021
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33466	0110182	V102614	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103296

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33467	0110182	V102556	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103297

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33468	0110182	V102566	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103298

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33469	0110182	V102578	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103299

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33470	0110182	V102587	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103300

Service Repair Sheet 67766

Contact Name	Ryan Curzon
Company/ Hospital Name	Gemco
General Phone	0844 24 98 102
Opera Account	00020099
Email	Ryan.Curzon@gemco.co.uk
Date Received	22/Mar/2021
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33471	0110182	V102555	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103301

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33472	0110182	V102586	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103302

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33473	0110182	V102609	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103303

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33474	0110182	V102562	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103304

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33475	0110182	V102579	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103305

Service Repair Sheet 67766

Contact Name	Ryan Curzon
Company/ Hospital Name	Gemco
General Phone	0844 24 98 102
Opera Account	00020099
Email	Ryan.Curzon@gemco.co.uk
Date Received	22/Mar/2021
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33476	0110182	V102606	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103306

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33477	0110182	V102619	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103307

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33478	0110182	V102598	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103308

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33479	0110182	V102574	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103309

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33480	0110182	V102597	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103310

Service Repair Sheet 67766

Contact Name	Ryan Curzon
Company/ Hospital Name	Gemco
General Phone	0844 24 98 102
Opera Account	00020099
Email	Ryan.Curzon@gemco.co.uk
Date Received	22/Mar/2021
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33481	0110182	V102565	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103311

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33482	0110182	V102607	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103312

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33483	0110182	V102573	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103313

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33484	0110182	V102560	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103314

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33485	0110182	V102612	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103315

Service Repair Sheet 67766

Contact Name	Ryan Curzon
Company/ Hospital Name	Gemco
General Phone	0844 24 98 102
Opera Account	00020099
Email	Ryan.Curzon@gemco.co.uk
Date Received	22/Mar/2021
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33486	0110182	V102581	Oxygen Sensor	
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103316

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33487	0110182	V102620	Oxygen Sensor	
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103317

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33488	0110182	V102590	Oxygen Sensor	
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103318

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33489	0110182	V102558	Oxygen Sensor	
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103319

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33494	0110182	V102603	Oxygen Sensor	
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103320