Contact Name Ryan Curzon
Company/ Hospital Name Gemco

General Phone 0844 24 98 102
Opera Account 00020099

Email Ryan.Curzon@gemco.co.uk

Date Received 22/Mar/2021 Booked in By Catherine Spence

Repair Ref S/N Equipment Type Under Warranty

SRN33466 0110182 V102614 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103296

Repair Ref S/N Equipment Type Under Warranty

SRN33467 0110182 V102556 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103297

Repair Ref S/N Equipment Type Under Warranty

SRN33468 0110182 V102566 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103298

Repair Ref S/N Equipment Type Under Warranty

SRN33469 0110182 V102578 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103299

Repair Ref S/N Equipment Type Under Warranty

SRN33470 0110182 V102587 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Contact Name Ryan Curzon Company/ Hospital Name Gemco

General Phone 0844 24 98 102 Opera Account 00020099

Email Ryan.Curzon@gemco.co.uk

Date Received 22/Mar/2021 Booked in By Catherine Spence

Repair Ref S/N Equipment Type Under Warranty

SRN33471 0110182 V102555 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103301

Repair Ref S/N Equipment Type Under Warranty

SRN33472 0110182 V102586 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103302

Repair Ref S/N Equipment Type Under Warranty

SRN33473 0110182 V102609 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103303

Repair Ref S/N Equipment Type Under Warranty

SRN33474 0110182 V102562 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103304

Repair Ref S/N Equipment Type Under Warranty

SRN33475 0110182 V102579 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Contact Name Ryan Curzon Company/ Hospital Name Gemco

General Phone 0844 24 98 102 Opera Account 00020099

Email Ryan.Curzon@gemco.co.uk

Date Received 22/Mar/2021 Booked in By Catherine Spence

Repair Ref S/N Equipment Type Under Warranty

SRN33476 0110182 V102606 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103306

Repair Ref S/N Equipment Type Under Warranty

SRN33477 0110182 V102619 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103307

Repair Ref S/N Equipment Type Under Warranty

SRN33478 0110182 V102598 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103308

Repair Ref S/N Equipment Type Under Warranty

SRN33479 0110182 V102574 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103309

Repair Ref S/N Equipment Type Under Warranty

SRN33480 0110182 V102597 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Contact Name Ryan Curzon
Company/ Hospital Name Gemco

General Phone 0844 24 98 102 Opera Account 00020099

Email Ryan.Curzon@gemco.co.uk

Date Received 22/Mar/2021 Booked in By Catherine Spence

Repair Ref S/N Equipment Type Under Warranty

SRN33481 0110182 V102565 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103311

Repair Ref S/N Equipment Type Under Warranty

SRN33482 0110182 V102607 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103312

Repair Ref S/N Equipment Type Under Warranty

SRN33483 0110182 V102573 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103313

Repair Ref S/N Equipment Type Under Warranty

SRN33484 0110182 V102560 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103314

Repair Ref S/N Equipment Type Under Warranty

SRN33485 0110182 V102612 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Contact Name Ryan Curzon
Company/ Hospital Name Gemco

General Phone 0844 24 98 102 Opera Account 00020099

Email Ryan.Curzon@gemco.co.uk

Date Received 22/Mar/2021 Booked in By Catherine Spence

Repair Ref S/N Equipment Type Under Warranty

SRN33486 0110182 V102581 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103316

Repair Ref S/N Equipment Type Under Warranty

SRN33487 0110182 V102620 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103317

Repair Ref S/N Equipment Type Under Warranty

SRN33488 0110182 V102590 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103318

Repair Ref S/N Equipment Type Under Warranty

SRN33489 0110182 V102558 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V103319

Repair Ref S/N Equipment Type Under Warranty

SRN33494 0110182 V102603 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG