



VANDAGRAPH
L I M I T E D

Service Repair Sheet 67785

Contact Name	Dave Blackmore
Company/ Hospital Name	Dave Blackmore
General Phone	07913 610378
Opera Account	CID17089
Date Received	06/Apr/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN33543	7910100	00720	Oxygen Analyser VN202	Complete - Repaired Time :0 Hour(s)

The VN202mk2 analyser has been repaired. The sensor input connector has been rewired.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33544	0110217	509817	Oxygen Sensor Vandagraph	No Fault Found Time :0 Hour(s)

The R-17VAN Oxygen sensor has been tested in air and Oxygen. No fault was found.

Repair	Ref	S/N	Equipment Type	
SRN33545	0131203	0000770	Oxygen Monitor Cable	No Fault Found Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.

15 Station Road • Cross Hills • Keighley
West Yorkshire • BD20 7DT • United Kingdom
Telephone: + 44 (0) 1535 634900
Fax: + 44 (0) 1535 635582
email: info@vandagraph.co.uk
www.vandagraph.co.uk

Company Registration • 23322105