

Service Repair Sheet SRS67805

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 20 Apr 2021

Mick Smithson

Lamboo Medical (UK)

07591 827595

01942 724 272

00013111

Mick@lamboo-medical.com

19/Apr/2021

Catherine Spence

Viamed

Warranty

Notes 15/Apr/2021 Steve Hardaker

15/Apr/2021 Steve Hardaker

15/Apr/2021 Steve Hardaker

Is returning a MaxO2-ME that they have just received, s/n FL71999001, sold 5/3/21.

Displaying Error E06 - Non-compatible oxygen sensor. They have tried another sensor and have tried removing/replacing batteries but it s still the same.

Please repair/replace ASAP, they need this back urgently.

19/Apr/2021 Catherine Spence

received in with oxygen sensor s/n FL23499014

No original packaging returned

put batteries in and is showing E06 error

Ready For quote

Repair Complete Signed

CGNEON 19.4.2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33620	Oxygen Monitor	0111263	FL71999001	Yes

0140020 x 1 @ £0
S/N, SRS, SRN
warranty repair

0111263 - x 1 @ £0
new S/N, SRS, SRN
warranty replacement
UPS x 1 @ £0