

Service Repair Sheet SRS67817

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Anita Birkett

Lincoln County Hospital

Clinical Engineering

Specialist Clinical Engineering Technician

01522 573663

0152 251 2512

00002610

Anita.Birkett@ulh.nhs.uk

04/May/2021

Robert Connor

Viamed

Warranty

Notes 28/Apr/2021 Zoey Teal

28/Apr/2021 Zoey Teal

Sending in a faulty T-7 sensor purchased in March. Serial number 590756. The sensor is only reading 60% in 100% oxygen.

04/May/2021 Robert Connor

1 x T-7 s/n 590756, with flow diverter

Ready For quote

Repair Complete Signed

C. GREGG 4-5-2021

| SRN      | Equipment     | Stock Ref | Serial Number | Warranty |
|----------|---------------|-----------|---------------|----------|
| SRN33665 | Oxygen Sensor | 0110057   | 590756        | Yes      |

0140013 x 1 @ £0  
old S/N, SRS, S/N

0110057 x 1 @ £0  
new S/N, SRS, S/N

UPS x 1 @ £0.

Lincoln County Hospital  
Greetwell Road  
Lincoln  
LN2 5QY

Enclosed is the  
faulty sensor s/n 590756,  
returns number SRS67817.

Yours sincerely

Anita Birkett

Mrs Anita Birkett  
Specialist Clinical Engineering Technician  
Clinical Engineering Dept  
Direct Dial: +44 (0) 1522 573663  
Email: [Anita.Birkett@ulh.nhs.uk](mailto:Anita.Birkett@ulh.nhs.uk)



| SRN      | Equipment     | Stock Ref | Serial Number | Warranty |
|----------|---------------|-----------|---------------|----------|
| SRN33665 | Oxygen Sensor | 0110057   | 590756        | Yes      |

0140013 x 1 @ £0  
old S/N, SRS, SRN

0110057 x 1 @ £0  
new S/N, SRS, SRN

UPS x 1 @ £0.