

Service Repair Sheet 67791
 Contact Name Nathan Grant
 Company/ Hospital Name Alder Hey Childrens Hospital
 Department Bio-Medical Engineering
 Position Medical Engineer
 Direct Phone 0151 252 5293
 General Phone 0151 228 4811
 Opera Account 00012595
 Date Received 26/May/2021
 Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33708	0110043	V106282	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110043 Oxygen sensor R-43V. Pack of 2 sensors.

24.0 in air and 113.4 in oxygen. This is low output and replaced under warranty with S/N V107679 / V107652

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33709	0110043	V106354	Oxygen Sensor	

Time :0 Hour(s)

27.8 in air and 131.3 in oxygen. This sensor is ok but its partner has failed. Replaced under warranty with S/N V107679 / V107652

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33710	0110043	V106698	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110043 Oxygen sensor R-43V. Pack of 2 sensors.

26.7 in air and 126.1 in oxygen. This sensor is ok but its partner has failed. Replaced under warranty with S/N V107680 / V107792

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33711	0110043	V106712	Oxygen Sensor	

Time :0 Hour(s)

30.2 in air and 136.6 in oxygen. This sensor is nonlinear and replaced under warranty with S/N V107680 / V107792
