Service Repair Sheet SRS67837

Contact Name

Company/ Hospital Name

Department

Position

**Direct Phone** 

General Phone

Opera Account

Email

Order Number

**Date Received** 

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Roger Thomas

Neath Port Talbot Hospital

**EBME** Department

**EBME** Engineer

01639 8620121

00012163

roger.thomas2@wales.nhs.uk

24/May/2021

Robert Connor

Viamed

Repair

Notes 18/May/2021 Steve Hardaker

18/May/2021 Steve Hardaker

18/May/2021 Steve Hardaker

Returning a Microstim s/n M0004678 for a fixed cost repair.

24/May/2021 Robert Connor

Received 1 x DB3 s/n M0004678, in grey case with patient lead, faulty control knob

Ready For quote

CGNOON 28-5-2021

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
34401111232	Microstim DB3	2510000	M0004678	2

2540010 × 1 2 ELS

SIN, SRS, SRN.

x 10 E10.







## Returns/Despatch Form

То	VIAN	1ED	From	ROGER THOMAS		
Address	Viam	ed Limited,	Address	Neath and Port Talbot		
	15 St	ation Road,		Hospital, EBME Dept,		
	Keigh	nley,		Baglan Way,		
	West	Yorkshire.		Port Talbot.		
Post Code	BD20	7DT	Post Code	SA12 7BX		
Your Ref	Nerv	e Stimulator	<b>2</b>	01639 862121		
			<b>~</b> ∂	roger.thomas2@wales.nhs.uk		
Date ,	19 M	ay 2021	Our Ref	30266546		
	126	FDNAS	8			
User Department EBME				Quantity Shipped 1		
Method of Shipping Post ☐ In Person ☐ Courier ☑						
RMA No. (or equivalent) N/A Name/Courier						
Manufacture		Viamed	Model DB	13		
Serial Numb	mber(s) M0004678					
Accessories <u>leads</u>						
Reason for Return/Despatch						
Control knob is faulty						
			- ×	<del></del>		
Further Comment/Instruction						
				*		
2						
-						