

Service Repair Sheet SRS67695

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Petr Tajc

Company/ Hospital Name

Divesoft

Department

Position

Direct Phone

+420 727 875 951

General Phone

Opera Account

Email

petr.tajc@divesoft.com

Order Number

Date Received

19/Jan/2021

Booked in By

Catherine Spence

Main Company

VandagraphST

Type Return

Warranty

Notes 11/Jan/2021 Sarah Walton

11/Jan/2021 Sarah Walton

SN. D105832, batch 2020/07 problem with connector. Returning for investigation

19/Jan/2021 Catherine Spence

received in

03/Feb/2021 Catherine Spence

Scanned to rma

26/Feb/2021 Catherine Spence

pending being sent back to supplier, eerror in the rma , need to get ammended

02/Mar/2021 Catherine Spence

in box 771

07/Mar/2021 Catherine Spence

with supplier

22/Apr/2021 Catherine Spence

Shipped back to supplier 05/03/2021 RMA300235180 requested update today

27/Apr/2021 Catherine Spence

requested an update from supplier by email 22/04/2021

19/May/2021 Catherine Spence

still with supplier

01/Jun/2021 Catherine Spence

will chase again, still with supplier

10/Jun/2021 Catherine Spence

supplier has said we will get a credit for this

Ready For quote

Repair Complete Signed

C. G. N. 11-6-2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33339	Oxygen Sensor VST	8010020	D105832	7

AS per Steve Nixon  
via Skype

8010020 x 1 FOC

S/N D105832

SRS 67695

SRN33339 unstable out put signal

~~ADD~~ Edie CST129799.