

Service Repair Sheet 67865

Contact Name	Alvin Manaloto
Company/ Hospital Name	Eastbourne District General Hospital
Department	EME Department
Position	EME Technician
Direct Phone	03001315151 Ext: 735151
Opera Account	00004621
Email	alvin.manaloto@nhs.net
Date Received	21/Jun/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33939	0111230	334659	Oxygen Monitor	No Fault Found Time :0 Hour(s)

The AX300i Oxygen monitor has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33940	0131202	0012426	Oxygen Monitor Cable	No Fault Found Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33941	0110017	593247	Oxygen Sensor	Time :0 Hour(s)

Parts Replaced

Qty: 1	0110017	Oxygen sensor R-17MED
--------	---------	-----------------------

The R-17MED Oxygen sensor has been replaced under warranty with SN:605828.
