

Service Repair Sheet SRS67870

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Stephen Linton

Antrim Area Hospital

Clinical Engineering Department

02894424000

00000126

Stephen.Linton@northerntrust.hscni.net

22/Jun/2021

Robert Connor

Viamed

Warranty

Notes 17/Jun/2021 Zoey Teal

17/Jun/2021 Zoey Teal

Sending in a faulty pair of R-22Vi sensors. Serial numbers V103500/501

22/Jun/2021 Robert Connor

2 x R22Vi s/n V103500, V103501

Molex connector loose

Ready For quote

Repair Complete Signed

CCGreen 24.6.2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33943	Oxygen Sensor	0110072	V103500/V103501	Yes

0140013 x 1 FOC
S/N, SRS, SRN

0110072 x 1 FOC
NEWS/N, SRS, SRN

OPS x 1 FOC

Clinical Engineering
Antrim Hospital
Bush Road
Antrim
BT41 2RL

Return reference number SRS67870

Serial Numbers of matched oxygen sensors return under warranty
V103500
V103501

Regards
Stephen Linton

Stephen.linton@northerntrust.hscni.net