

Service Repair Sheet 67870

Contact Name	Stephen Linton
Company/ Hospital Name	Antrim Area Hospital
Department	Clinical Engineering Department
General Phone	02894424000
Opera Account	00000126
Email	Stephen.Linton@northerntrust.hscni.net
Date Received	22/Jun/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33943	0110072	V103500/V103501	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110072 Oxygen sensor R-22Vi. Pack of 2

These have a visibly faulty connector. Replaced under warranty with S/N V104521/V104522
